

Engine Air Filter – 2009-2016 3.5L Chevrolet Impala

Required Tools

- 8mm socket
- Ratchet or Impact Gun
- Flathead Screwdriver

General Repair Steps

1. Remove Mass Airflow Sensor electrical cable.
2. Loosen and remove Air Cleaner Outlet Duct.
3. Disconnect clips on top of Engine Air Filter housing.
4. Remove cover on housing.
5. Remove dirty Engine Air Filter.
6. Insert new Engine Air Filter.
7. Replace housing cover.
8. Reconnect clips.
9. Reconnect and tighten Air Cleaner Outlet Duct.
10. Reconnect Mass Airflow Sensor electrical cable.