










May 27, 2015 7:57 AM

VIN retrieved from Vehicle
VIN: 1D7HU18276S580384
Make:Dodge Year:2006








 Smog Readiness Check Failed 
Address issues below before Smog Check

-  Check Engine Light ON
-  10 Confirmed Trouble Codes
-  10 Pending Trouble Codes

Common I/M Monitors

-  Misfire Test is complete
-  Fuel System Test is complete
-  Comprehensive Component Test is complete
-  EGR and/or VVT System Test is NOT complete

Spark Engine I/M Monitors

-  Catalyst Test is NOT complete
-  Heated Catalyst Test is not applicable
-  Evaporative System Test is NOT complete
-  Secondary Air System Test is not applicable
-  A/C Refrigerant Test is not applicable
-  Oxygen Sensor Test is NOT complete
-  Oxygen Sensor Heater Test is NOT complete

Vehicle Protocol: CAN11_500
Sensor F/W Version: OSAPI v2.30
App Version: QA-264

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at www.lemurmonitors.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.